Site Name: Operational Period: U.S. EPA Region 6 Task Order 62 CES Environmental Date: 5-20-2015 DAILY WORK ORDER Division/ Branch: Federal Response **Emergency and Rapid Response Service** Group: WORK AUTHORIZED: Continue to pump water on site as necessary, depending on rainfall. Continue development of profiles and disposal of sludge, liquids, and solids. Continue removal of water, oil, sludge, and waste, from the ASTs, Frac Tanks, Totes, and Drums. Site Cerclis:# On-Scene Coordinator: ERRS Response Manager TXD 008950461 EP - S6 - 07 -02 Gary Moore, USEPA Contract Number LeRoy Cassidey, CB&I Federal Task Order: 062 Date: 5.20.2015 Time: 1700 Date: 5.20.2015 Time: 1700 EQUIPMENT ON-PERSONNEL ON-SITE: QTY Used Unused QTY USED Unused SITE: Response Manager 1 Pick -up Truck 2 2 1 1 Foreman Generator 1 1 Equipment Operator 0 0 Trash Pumps 0 0 Truck Driver 1 1 **Utility Trailer** 0 0 Frac Tank w Liner Laborer 2 2 1 1 4,000 PSI Pressure Health and Safety Manager 0 0 1 1 Washer PERSONNEL OFF-SITE Open Top Roll Off 5 5 Subcontract Manager 1 1 Vacuum Truck Air Mover 1 1 Transport and Disposal Coord 1 1 Carbon Vapor Unit 0 0 Field Cost Accountant 1 1 Skid Steer 0 0 Vacuum/OT Boxes 14 14 9,000 lb Overhead Lift 1 1 Storage Trailer 1 1 1 Myers (Bean) Pump 1 Air Compressor 1 1 WORK ACCOMPLISHED / AMENDMENTS (problem areas, general comments, summary)(Input for day's 1, 900-5Pon5): The RM continued processing of operational-H/Safety paperwork, procurements, and invoices. Continued to work with subcontractors on FT 1004 transport to TIBM. Worked on transition to Mike Means during vacation. Scheduled, manifested VB 25147 to Republic Services, Blue Ridge Landfill. T&D Coordinator worked on transition to Mike Means, Greg Norden during vacation. The crew started the lime removal into VB 25315. Continued to clean and pressure wash the Washing Bays area and sumps. They removed the water from the South Pond and fixed hay bales around the North drain. Date: Time: Date: 5.20.2015 Time:1100 5/21/15 1720

Next OPERATIONAL PERIOD (administrative, tactical / status changes, special instructions, H&S)(Input for next DWO):

Continue lime removal residual into VB 25229. Continue cleaning and pressure washing the remaining totes. Prepare, OT 25563, OT 25319, OT 25134 and OT 25165 for disposal.

Continue to sample, profile, and schedule waste for final transportation and disposal. Continue to process invoices, set up procurements and track costs. Continue set up for FT 1004 transport to TIBM and lime transport to US Lime Company.